

3-23-2016
Davis Lake-Charlotte - Wet Pond 1
Wet Pond

Prepared By Trevor Andrews
 trevor@fosterlake.com

Structural Observations

Inlets	Functioning as Intended
Outlets	Functioning as Intended
Ditches, swales, channels	Not Applicable
Drainage structures	Functioning as Intended
Forebay	Not Applicable
Slopes, embankments	Functioning as Intended
Dam	Functioning as Intended
Littorial Shelf	Not Applicable
Enhancements	Not Applicable

Structural Observation Notes

- Muskrat holes persist around parts of shoreline.
- Outlet devices draining water as intended.
- Some bare soil on dam. Have landscapers re seed and cover with erosion fabric.
- Inlets functioning as intended.

Maintenance Activities

Trash Removed	Yes
Grates, racks, risers cleaned	Not Applicable
Erosion repair	Not Applicable
Nuisance vegetation treated	Not Applicable

Nuisance animal control effort	No
Water quality tested	Yes
Fish stocked	Not Applicable
Fisheries sampled	Not Applicable
Fish feeder maintenance	Not Applicable
Aeration/Fountain maintenance	Not Applicable
Valve(s) exercised	Not Applicable
Aquatic plants (desirable) maintenance	Not Applicable
Mowing	Not Applicable
Brush clearing	Not Applicable
Tree removal	Not Applicable

Maintenance Activity Notes

- Removed trash
- Inspected outlet devices. Functioning as intended.
- Inspected inlets. Functioning as intended.

Recommendations/Additional Notes
